

TABLE OF CONTENTS

PREFACE	XXIX
ORGANIZATION.....	XXXI

Volume 1

KEYNOTE LECTURES

<i>A. Di Tommaso</i> STRUCTURAL CONSERVATION OF HISTORICAL CONSTRUCTIONS USING COMPOSITE MATERIALS TECHNIQUE	3
<i>A. Baratta, O. Corbi</i> THE STATIC BEHAVIOUR OF THE HISTORICAL CUPOLAS.....	15
<i>J. Bień, R. Helmerich</i> THEORETICAL AND EXPERIMENTAL ANALYSIS OF HISTORICAL BRIDGES.....	45
<i>J. Kościuk</i> MODERN 3D SCANNING IN MODELING, DOCUMENTATION AND CONSERVATION OF ARCHITECTURAL HERITAGE	64
<i>S. M. Holzer</i> NUMERICAL ARCH AND VAULT ANALYSIS.....	77
<i>J. M. Izquierdo-Encarnación</i> CODES AND SPECIFICATIONS AS APPLIED TO HISTORIC PRESERVATION PROJECTS.....	94
<i>B. Szabo, I. Kirizsán</i> EUROPEAN HISTORIC ROOF STRUCTURES: CONCEPTS OF COMPOSITION AND INTERVENTION.....	105
<i>L. Priya</i> CONSERVATION OF INDIAN HERITAGE SITES: A MULTIDISCIPLINARY INTEGRATED APPROACH.....	128
<i>J. Ochsendorf</i> STRUCTURAL ASSESSMENT OF MASONRY VAULTS: LESSONS FOR PRESERVATION ENGINEERING.....	133
<i>M. Golabchi</i> CONSERVATION, REPAIR AND EXTENSION OF IMAM REZA HOLY SHRINE	141
<i>G. de Felice, O. Al Shawa, A. Mauro, L. Sorrentino</i> ON THE SEISMIC BEHAVIOUR OF OUT-OF-PLANE LOADED MASONRY WALLS.....	150

A. Kadłuczka
ARCHITECTURAL HERITAGE AND NEW USES. PRINCIPLES AND DOCTRINES 159

C. Blasi, F. Ottoni
THE ROLE OF STRUCTURAL MONITORING IN HISTORICAL
BUILDING CONSERVATION 166

STRUCTURAL ANALYSIS AND SAFETY ASSESSMENT

A. Alonso Durá, A. Martínez Boquera, V. Llopis Pulido, J. Moreno Puchalt
STRUCTURAL BEHAVIOUR ANALYSIS OF THE DOME
OF THE CATHEDRAL OF VALENCIA 185

J.-U. Anwand, J. Fleischer, M. Kröning, U. Schröter, D. Wendland
A MASONRY STRUCTURE WITH COMPLEX GEOMETRY:
RECONSTRUCTING THE LATE-GOTHIC VAULT IN THE PALACE CHAPEL
AT DRESDEN USING TRADITIONAL BUILDING TECHNIQUE 193

A. Anzani, A. Baila, P. Bamonte, P. Condoleo, C. Togiani
STRUCTURAL SURVEY OF A CHIMNEY BETWEEN XIX AND XX CENTURY 201

G. Boscato, A. Dal Cin, D. Rocchi, S. Russo, F. Sciarretta, E. Sperotto, M. Tommasini
STRUCTURAL IDENTIFICATION OF DAMAGED ANIME SANTE CHURCH USING
AMBIENT VIBRATION, FORCED VIBRATION AND EARTHQUAKE ACTION 209

P. Clemente, G. Buffarini , L. Platania, F. Saitta
STATIC AND DYNAMIC ANALYSES OF THE MINARET IN JAM 218

Q. Collette, S. Vanbeveren, P. Stoffel
STRUCTURAL ANALYSIS OF HISTORICAL REINFORCED CONCRETE STRUCTURE:
CASE STUDY OF THE DOTREMONT HOUSE (1932) 226

V. Compán, M. Cámera, J. Sánchez
STRUCTURAL ANALYSIS OF COMPLEX FORMS IN THE GERMAN BAROQUE 235

I. de Vent, J. Rots, R. Van Hees, G. Hobbelman
CONFUSING CRACKS AND DIFFICULT DEFORMATIONS:
INTERPRETING STRUCTURAL DAMAGE IN MASONRY 243

A. Gubana, I. Di Gianantonio
TRIUMPHAL ARCH COLLAPSE MECHANISMS 253

D. Häfner
THE “ELLIPTICAL BEAMS” IN THE WINTER PALACE
IN SAINT PETERSBURG – STRUCTURAL ASSESSMENT
OF A LIGHTWEIGHT STRUCTURE 262

M. Hejazi, M. Daei, S.M. Moayedian, B. Hejazi
STRUCTURAL ANALYSIS OF PERSIAN HISTORICAL BRICK MASONRY MINARETS 273

M. Hejazi, M. Vafaeian, A.H. Farmanara Bozorgzad
FOUNDATION SETTLEMENTS OF THE HISTORICAL BUILDING OF CHAHAR-BAGH
MADRASSA CAUSED BY VIBRATIONS INDUCED BY UNDERGROUND TRAINS 282

R. Korenkova , P. Krusinsky, F. Bahleda , K. Ďurian
STATIC ANALYSIS OF HANGING TRUSS OF BEAMED FLOOR
IN EVANGELICAL CHURCH IN VYSNA BOCA 289

<i>D.F. Laefer, D. Murphy</i>	
CHARACTERISTIC DAMAGE CONCENTRATION:	
A NEW DAMAGE INDEX FOR HISTORIC INTERIORS.....	297
<i>P.B. Lourenço, M. Filippoupolitis, C. Corallo, N. Mendes</i>	
SAFETY ASSESSMENT OF THE SOUTH OCULUS, CANTERBURY CATHEDRAL (UK)	302
<i>A. Lozano, M. Guaita, J. Portela, J.J. Del Coz, M. Serrano</i>	
CAUSES OF THE COLLAPSE OF THE FRONT OF THE MONASTERY	
OF SAN PELAYO (SPAIN)	311
<i>P. Matracchi, L. Giorgi</i>	
NEW INSIGHTS ON THE STRUCTURAL WEAKNESS	
OF THE DUOMO NUOVO IN SIENA	317
<i>F. Muñoz, F. Peña, M. Meza</i>	
STRUCTURAL ASSESSMENT OF ARCHITECTURAL HERITAGE BUILDINGS	
BY MEANS OF VIRTUAL REALITY MODELS.....	325
<i>F. Pena, M. Meza, M. Chavez</i>	
MACROELEMENT IDENTIFICATION OF MASONRY CHURCHES	
BY MEANS OF THEIR DYNAMIC PROPERTIES.....	333
<i>E. Quagliarini, F. Monni, S. Lenci</i>	
IMPORTANCE OF BUILDING KNOWLEDGE FOR A CORRECT STRUCTURAL	
ASSESSMENT. THE CASE OF SANTA MARIA DELLA CARITÀ CHURCH	
IN ASCOLI PICENO (ITALY).....	341
<i>G.M. Roberti, M. Bondanelli, F. Trovò</i>	
A SAFETY INDEX EVALUATION FOR MASONRY BELL TOWERS IN VENICE	351
<i>P. Roca, M. Cervera, L. Pelà, R. Clemente, M. Chiumenti</i>	
STRUCTURAL ASSESSMENT OF MALLORCA CATHEDRAL	359
<i>D. Uglešić, A. Uglešić</i>	
PROTIIRON OF THE PERISTYLE IN THE PALACE OF DiOCLETIAN IN SPLIT	368
<i>L. Van Parys, J. Noël, D. Lamblin , S. Datoussaid, A. Tilmant</i>	
DISORDERS IN NORTH TRANSEPT OF THE CATHEDRAL IN TOURNAI (BE):	
STRUCTURAL MONITORING, SIMULATIONS AND TEMPORARY STABILIZATION	377
<i>J. Yuan, Y. Shi</i>	
SIMULATION AND EXPERIMENTAL RESEARCH ON ENERGY DISSIPATION	
BEHAVIOR OF DOU-GONG.....	385

ANALYTICAL AND NUMERICAL APPROACHES

<i>A. Albuerne, M. Williams, V. Lawson</i>	
PREDICTION OF FAILURE MECHANISM OF ARCHES AND BARREL VAULTS	
UNDER BASE MOTION USING THE NSCD METHOD.....	397
<i>A. Ayensa Pardo, B. Beltrán Pellicer, E. Ibarz Montaner, L. Gracia Villa</i>	
A METHODOLOGY FOR THE ASSESSMENT OF HISTORICAL STRUCTURES	
BASED ON FINITE ELEMENT MODELS	407
<i>R. Barsotti, S. Bennati</i>	
MECHANICAL BEHAVIOUR OF MASONRY PANELS UNDER IN-PLANE LOADS	416

<i>P. Block, L. Lachauer</i>	
THREE-DIMENSIONAL EQUILIBRIUM ANALYSIS OF GOTHIC MASONRY VAULTS	424
<i>C. Camós, C. Molins, O. Arnau, J. Gálvez</i>	
NUMERICAL SIMULATION OF THE STRUCTURAL BEHAVIOUR OF BUILDINGS UNDER TUNNELLING INDUCED SETTLEMENTS: A CASE STUDY IN THE L9 METRO LINE (BARCELONA).....	432
<i>C. Casapulla, F. Portioli, A. Maione, R. Landolfo</i>	
MACRO AND MICRO-BLOCK MODELLING FOR LIMIT ANALYSIS OF MASONRY STRUCTURES WITH NON-ASSOCIATIVE FRICTIONAL JOINTS	441
<i>N. Cavalagli, V. Gusella, F. Vittori</i>	
ON THE CONTRIBUTION OF BERNARDO VITTORE IN THE DESIGN OF MASONRY DOMES	449
<i>A. Cecchi</i>	
THE CURVE OF PRESSURE IN VERTICALLY LOADED ARCHES	457
<i>A. Costa, J. Lluis i Ginovart, G. Fortuny, P. Solà-Morales</i>	
LIMIT ANALYSIS OF MASONRY DOME COLLAPSE MECHANISMS BY MEANS OF FINITE ELEMENTS	465
<i>G. Giardina, S. Boldrini , M. A. N. Hendriks, J. G. Rots</i>	
PILE FOUNDATION IN 3D MODELLING OF BUILDING DAMAGE DUE TO SETTLEMENT.....	473
<i>M. Guadagnuolo, A. Donadio, G. Faella</i>	
OUT-OF-PLANE FAILURE MECHANISM OF MASONRY BUILDING CORNERS	481
<i>M. Lippiello, F. Portioli, C. Ceraldi, R. Landolfo</i>	
MASONRY DOMES STRENGTHENING: A COMPARATIVE STRUCTURAL ANALYSIS	489
<i>G. Milani, M. Pizzolato, A. Tralli</i>	
SIMPLE HOMOGENIZED PLATE MODEL FOR OUT-OF-PLANE LOADED MASONRY TAKING INTO ACCOUNT MATERIAL AND GEOMETRICAL NON LINEARITY	498
<i>M. Paradiso, G. Tempesta, S. Galassi, E. Perria, G. Berti</i>	
DEGRADATION AND CONSOLIDATION OF THE DOME OD THE CATHEDRAL OF SANTIAGO DE CUBA.....	508
<i>B. Peng, X.L. Gu, Y. Ouyang, K. Sun, N.K. Liu</i>	
NUMERICAL SIMULATION FOR RETROFIT OF THE ANDREWS & GEORGE BUILDING IN SHANGHAI	517
<i>M. Pilar Giraldo, V. Rodríguez, C. Burgos</i>	
NUMERICAL-SIMULATION RESEARCH ON FIRE BEHAVIOR OF A HISTORIC INDUSTRIAL BUILDING	525
<i>F. Portioli, L. Cascini, C. Casapulla, M. D'Aniello, R. Landolfo</i>	
LIMIT ANALYSIS OF CONFINED MASONRY SHEAR WALLS BY RIGID BLOCK MODELING WITH CRACKING UNITS	534
<i>E. Rizzi, G. Colasante, A. Frigerio, G. Cocchetti</i>	
ON THE MIXED COLLAPSE MECHANISM OF SEMI-CIRCULAR MASONRY ARCHES.....	541
<i>E. Sacco</i>	
STRESS APPROACHES FOR THE ANALYSIS OF MASONRY ARCHES.....	550

<i>V. Sarhosis, S. Garrity, Y. Sheng</i>	A COMPUTATIONAL MODELLING APPROACH FOR LOW BOND STRENGTH MASONRY.....	559
<i>M. Sebastianelli, A. Amorosi, D. Boldini, G. de Felice, G. Di Mucci, M. Malena</i>	SETTLEMENT PREDICTION OF AN HISTORIC MASONRY DUE TO TUNNEL EXCAVATION TAKING INTO ACCOUNT SOIL-STRUCTURE INTERACTION.....	567
<i>B. Silva, A. Pappas, M. R. Valluzzi, F. da Porto, C. Modena</i>	CALIBRATION OF A NUMERICAL MATERIAL BEHAVIOUR MODEL FOR THE SIMULATION OF MULTI-LEAF STONE MASONRY WALLS	575
<i>L. Van Parys, J. Noël, D. Lamblin, E. Bultot, L. Delehouzee</i>	FE “BLOCK & INTERACTION” APPROACH FOR ESTIMATING THE IMPACT OF BELL TOWER INCLINATIONS ON THE SAFETY OF NORTH TRANSEPT ARCH SYSTEM IN THE OL CATHEDRAL OF TOURNAI (BE)	584
<i>T. J. White, A. D. Sorensen</i>	NUMERICAL MODELING OF THE EFFECTS OF TEMPERATURE ON EXPERIMENTAL MODAL ANALYSIS DATA.....	594
<i>Pan Jianwu, Chun Qing</i>	FINITE ELEMENT ANALYSIS OF TAIZHOU WATER STATION SITE IN CHINA.....	601
EXPERIMENTAL ANALYSIS		
<i>Ch.-E. Adami, E. Vintzileou, Ch. Mouzakis, L. Karapitta</i>	DYNAMIC TESTS ON TIMBER-LACED THREE-LEAF STONE MASONRY MODEL.....	609
<i>J. Atalić, D. Lazarević, M. Šavor</i>	TRADITIONAL COLUMN CONNECTIONS WITH IRON DOWELS – EXPERIMENTAL AND NUMERICAL ANALYSIS	619
<i>P. Bocca, S. Valente, A. Grazzini, A. Alberto, V. Di Vasto</i>	DELAMINATION OF DEHUMIDIFIED REPAIR MORTARS: A NEW EXPERIMENTAL AND NUMERICAL ANALYSIS	628
<i>M. Bovo, C. Mazzotti, M. Savoia</i>	ANALYSIS OF STRUCTURAL BEHAVIOUR OF HISTORICAL STONE ARCHES AND VAULTS: EXPERIMENTAL TESTS AND NUMERICAL ANALYSES.....	635
<i>J. Brol, S. Dawczyński, A. Malczyk, K. Adamczyk</i>	TESTING TIMBER BEAMS AFTER 130 YEARS OF UTILIZATION.....	644
<i>M. Chávez, R. Sánchez, R. Meli</i>	CHARACTERIZATION OF THE HISTORIC MASONRY BUILDINGS OF MEXICO	651
<i>E. Gabrielli, C. Colla</i>	LABORATORY INVESTIGATION OF DAMP RISE IN POROUS MASONRY CONSTRUCTION MATERIALS	659
<i>L. Hojdys, P. Krajewski</i>	EXPERIMENTAL TESTS ON STRENGTHENED AND UNSTRENGTHENED MASONRY VAULT WITH BACKFILL.....	668
<i>X. Li, X.L. Gu, Z.N. Gao, Y. Ouyang, N.K. Liu</i>	DETERMINATION OF MECHANICAL PROPERTIES OF HISTORICAL BRICK MASONRY MATERIALS	675

<i>A.-A. Manoledaki, V. Drosos, I. Anastasopoulos, E. Vintzileou, G. Gazetas</i>	
OUT-OF-PLANE RESPONSE OF THREE-LEAF STONE MASONRY WALLS TAKING ACCOUNT OF SOIL-STRUCTURE INTERACTION: AN EXPERIMENTAL STUDY	684
<i>P. Marini, R. Bellopede</i>	
SANDSTONE DECAY: FROM HISTORICAL BUILDINGS TO LABORATORY TESTS	691
<i>J. Milosevic, A. S. Gago, M. Lopes, R. Bento</i>	
RUBBLE STONE MASONRY WALLS – EVALUATION OF SHEAR STRENGTH BY DIAGONAL COMPRESSION TESTS	697
<i>Ch. Mouzakis, E. Vintzileou, Ch.-E. Adami, L. Karapitta</i>	
DYNAMIC TESTS ON THREE LEAF STONE MASONRY BUILDING MODEL BEFORE AND AFTER INTERVENTIONS	706
<i>L. Pelà, A. Benedetti, D. Marastoni</i>	
INTERPRETATION OF EXPERIMENTAL TESTS ON SMALL SPECIMENS OF HISTORICAL MORTARS	716
<i>C. Sandoval, P. Roca</i>	
EXPERIMENTAL AND NUMERICAL STUDY OF THE BUCKLING FAILURE OF MASONRY WALLS.....	724
<i>H. Sung-Gul, H. K. Namhee, H. Tae-Wook</i>	
FRACTURE MECHANICS CHARATERISTICS OF FLEXURAL STRENGTH OF GRANITE STRUCTURAL COMPOENTS REINFORCED BY METAL.....	732
<i>A. Vatani Oskouei, M. Afzali, M. Madadipour</i>	
EFFECT OF LIME AND RICE HUSK ASH STABILIZATION AND COMPACTION ON MUD BRICK REINFORCED WITH SYNTHETIC FIBERS	740
 INNOVATIVE AND TRADITIONAL MATERIALS/TECHNIQUES	
<i>Ch.-E. Adami, E. Vintzileou, Ch. Mouzakis, E. Badogiannis, A. Kalagri</i>	
THE EFFECT OF HYDRAULIC LIME POZZOLANIC GROUTS ON THE MECHANICAL PROPERTIES OF THREE-LEAF STONE MASONRY IN COMPRESSION.....	751
<i>A. Ajdukiewicz, B. Kotala, M. Weglorz</i>	
CONCEPT AND PRACTICAL APPLICATIONS OF TEXTILE REINFORCED CONCRETE	760
<i>M. Avraham</i>	
REINFORCED CONCRETE AND CONSERVATION OF THE HERITAGE OF THE BUILT ENVIRONMENT	767
<i>E. Badogiannis, A. Miltiadou, A. Kalagri, E. Ipsilanti, C. Dedeloudis, E. Vintzileou</i>	
MIX DESIGN AND PERFORMANCE EVALUATION OF GROUTS WITH SUPERFINE NATURAL POZZOLAN	773
<i>D. Bansal, R. Gogia</i>	
INNOVATIVE AND TRADITIONAL BUILDING MATERIALS – SUSTAINABILITY & COST EFFECTIVENESS – AN ANALYSIS OF EEV	781
<i>G. De Blasi</i>	
TECHNOLOGICAL INNOVATION AND TRADITION IN THE MAINTENANCE STRATEGIES OF THE EUROPEAN CATHEDRALS. TWO CASE STUDIES: SANTA MARIA DEL FIORE, FLORENCE AND WELLS CATHEDRAL, WELLS	790

<i>A. Erdem, U. Yergun, N. Seçkin</i>	
A PIONEER EXAMPLE OF STEEL FRAME CONSTRUCTION IN OTTOMAN ARCHITECTURE: THE GREAT SYNAGOGUE OF EDIRNE.....	800
<i>B. Faggiano, M. R. Grippa, A. Marzo, F. M. Mazzolani</i>	
THE STEEL COLLAR CONNECTOR FOR COMPOSITE TIMBER-CONCRETE FLOOR: CONCEPTION, ANALYSIS AND APPLICATIONS.....	807
<i>T. Falborski, A. Kwiecień, M. Strankowski, Ł. Piszczyk, R. Jankowski</i>	
THE INFLUENCE OF TEMPERATURE ON PROPERTIES OF THE POLYMER FLEXIBLE JOINT USED FOR STRENGTHENING HISTORICAL MASONRIES	816
<i>A. Koss, J. Marczałk</i>	
EVALUATION OF LASER CLEANING PROGRESS AND QUALITY	823
<i>P. Larrinaga, D. García, L. Garmendia, J. Díez, J. T. San-José</i>	
PATHOLOGIES IN LOW-GRADE CONCRETE STRUCTURES AND TEXTILE REINFORCED MORTAR AS INNOVATIVE RETROFITTING SYSTEM.....	832
<i>L. Miccoli, U. Müller</i>	
CHARACTERISATION OF EARTHEN ELEMENTS. A COMPARISON BETWEEN EARTH BLOCK MASONRY, RAMMED EARTH AND COB.....	841
<i>O. Ç. Ozdemir, A. Ç. Gökyılmaz, B. Gökyılmaz</i>	
AN APPLICATION DIRECTED AT USING AUTHENTIC MATERIALS WHEN RENOVATING HISTORIC STRUCTURES	850
<i>H. Pachla, F. Pachla</i>	
REMARKS ON THE USEFULNESS OF DEEP FOUNDATIONS FOR THE STRENGTHENING OF FOUNDATIONS IN HISTORIC AREAS	859
<i>A. Pérez Zuniga</i>	
PRINCIPLES OF COMPOSITE CONSTRUCTION APPLIED TO STRUCTURAL REHABILITATION OF HISTORICAL CENTRES	867
<i>S. Pineda, R. Bustamante, N. Prendes</i>	
FERRUGINOUS SHALES LUTITIC SANDSTONE (EYE'STONE) MASONRY OF TRADITIONAL BUILDINGS IN MARACAIBO, VENEZUELA.....	874
<i>M. Přinosil, P. Kabele</i>	
PREDICTION OF THE BEHAVIOR OF LIME MORTAR REINFORCED WITH FIBERS BASED ON THEIR MICROMECHANICAL PARAMETERS	883
<i>R. Prusinski, W. S. Wahby</i>	
PRECAST POLYMER CONCRETE BUILDING PANELS: CASE STUDIES WITH LONGEVITY EXPERIENCE.....	890
<i>I. Rörig-Dalgaard</i>	
FIRST EXPERIENCES WITH ELECTROCHEMICAL IN-SITU DESALINATION OF BRICKS IN A CHURCH VAULT CONSTRUCTION	897
<i>A. Różańska, I. Burawska, A. Policińska-Serwa, W. Koryciński, A. Mazurek, P. Beer, I. Swaczyna</i>	
STUDY OF ANTIQUE WOODEN FLOOR ELEMENTS OF CHOSEN BUILDINGS FROM SOUTH-EASTERN POLAND	905
<i>A. Skorek</i>	
THE HISTORY OF ROMAN CEMENT AND ITS USE IN CONSERVATION OF ARCHITECTURAL MONUMENTS.....	914

<i>A. Vatani Oskouei, M. Afzali, M. Madadipour</i>	
EFFECT OF SOME NATURAL ADDITIVES ON THE MECHANICAL PROPERTIES OF MUD BRICK	920
<i>A. Vatani Oskouei, M. Madadipour, M. Afzali</i>	
EFFECT OF SOME SYNTHETIC FIBERS ON MECHANICAL PROPERTIES OF MUD BRICK	928
<i>E. Verstrynge, K. De Wilder, R. Timmermans, L. Schueremans, L. Vandewalle</i>	
RETROFITTING OF THIN CONCRETE SLABS WITH VARIOUS TYPES OF EXTERNALLY BONDED REINFORCEMENT	936
<i>W. S. Wahby</i>	
THE POSSIBLE UTILITY OF POLYMERS IN THE RESTORATION AND PRESERVATION OF EGYPT'S SPHINX	945
<i>J. Jayaprakash, Sharifah Salwa Mohd Zuki, Choong Kok Keong</i>	
A REVIEW ON REPAIR OF FIRE-DAMAGED CONCRETE COLUMNS WITH FIBRE REINFORCED POLYMER	953
<i>Dilek Ekşi Akbulut, Fevziye Aköz</i>	
EFFECTS OF POZZOLANAS AND FIBERS ON MECHANICAL PROPERTIES OF MORTARS IN HISTORICAL BUILDINGS	961
<i>Bekir Yilmaz Pekmezci, Hakan Nuri Atahan, Işıl Polat Pekmezci, Erman Yiğit Tuncel</i>	
EFFECTS OF LIME MORTAR DESIGN ON MECHANICAL PROPERTIES OF HISTORICAL MASONRY UNITS	969
AUTHOR INDEX	XXXIII

Volume 2

CONSERVATION AND HISTORY OF CONSTRUCTION BUILDING TECHNOLOGIES AND MATERIALS

<i>K. Afzali</i>	
ARCHITECTURE AND STRUCTURE DESIGN OF SOLTANIEH DOME OF IRAN	979
<i>K. Alykow, M. Napiórkowska-Alykow</i>	
THE INFLUENCE OF THE 19th CENTURY TECHNICAL SOLUTIONS OF THE WORK OF THE BAROQUE HALL CHURCHES.....	986
<i>G. Arun</i>	
TRADITIONAL TIMBER STRUCTURES IN TURKEY	995
<i>K. Babraj, J. P. Kogut, J. Zięba</i>	
NUMERICAL RECONSTRUCTION OF BEHAVIOUR OF THE ANCIENT POTTERY KILN FROM MAREA (EGYPT) DUE TO OPERATIONAL LOADING.....	1003
<i>D. Bajno</i>	
THE DETERMINATION OF CAUSES FOR DEFECTS OCCURRING IN THE SEVENTEENTH-CENTURY CHURCH BUILDING IN PRÓSZKÓW, OPOLE PROVINCE, POLAND	1015

<i>T. Basirico</i>	
THE „MIXED STRUCTURES” OF THE SANATORIUMS BUILT IN THE 30S IN ITALY	1021
<i>H. Cervinkova, J. Ilkocz</i>	
CENTENNIAL HALL IN WROCŁAW – CHALLENGES OF CONSTRUCTION AND PRESERVATION	1029
<i>S. Chatterjee</i>	
CRITICAL ISSUES OF LAYERED STONE CONSTRUCTIONS AND APPLICATION OF ARCHIVES IN INVESTIGATION – THE CASE OF VITTHALA TEMPLE, HAMPI WORLD HERITAGE SITE	1041
<i>M. Chorowska, P. Błoniewski</i>	
CONVERSION OF RUINS OF A MEDIEVAL CASTLE IN PŁONINA FOR TOURISTIC PURPOSES	1050
<i>A. Çiftçi</i>	
THE IMPORTED TILES AND ARCHITECTURAL CERAMICS USED IN 19-20TH CENTURY ISTANBUL’S BUILDINGS	1060
<i>Q. Collette, I. Wouters, C. De Favereau, A. Peters</i>	
DEVELOPMENT OF RIVETING TECHNOLOGY THROUGH AN ANALYSIS OF BELGIAN PATENTS (1830-1940)	1071
<i>Q. Collette, I. Wouters, L. Lauriks, K. Verswijver</i>	
MORPHOGENESIS OF THE THEORY AND DESIGN PRINCIPLES OF RIVETED CONNECTIONS IN HISTORICAL IRON AND STEEL STRUCTURES	1080
<i>M. Czarniecki, D. Czerek</i>	
RENOVATION OF THE CENTENNIAL HALL (UNESCO LIST, WROCLAW, POLAND)	1089
<i>D. De Mattia</i>	
THE BIRTH OF THE TECTONICS: FROM THE HISTORY OF CONSTRUCTION TO THE STRUCTURAL ANALYSIS AND ARCHITECTURAL DESIGN	1097
<i>L. Dekeyser, A. Verdonck, H. de Clercq, H. Wouters</i>	
‘MARBRITE FAUQUEZ’ OPALESCENT AND MASS COLOURED GLASS: HISTORY, PRODUCTION AND COMPOSITION	1106
<i>B. Demetrescu, V. Gioncu</i>	
HISTORICAL STRUCTURES IN THE ROMANIAN BANAT AREA.....	1114
<i>D. Friedman, G. Pardo Redondo</i>	
THE NEW YORK CRYSTAL PALACE: IRON STRUCTURE WITHOUT ENGINEERING	1119
<i>L. Giorgi, P. Matracchi</i>	
STABILITY OF THE STRUCTURE OF THE BASILICAN BODY OF SANTA MARIA DEL FIORE IN FLORENCE DURING CONSTRUCTION OF THE NAVES	1127
<i>A. Grimoldi, A. Landi</i>	
THE SPREAD OF THE XVIITH CENTURY VAULTS IN CREMONA. THE CASE-STUDY OF MAGIOGRASSELLI PALACE.....	1136
<i>A. Gryglewska</i>	
EXEMPLARY MATERIALS AND BUILDING TECHNOLOGIES IN THE HUNDRED-YEAR EDIFICE OF THE FORMER CONSTUCTION CRAFTS SCHOOL IN WROCŁAW	1145

<i>M. Hejazi, M. Daei, S. M. Moayedian, B. Hejazi</i>	PERSIAN MINARETS: HISTORY, CONSTRUCTION AND MATERIALS	1154
<i>A. Hellebois, B. Espion</i>	INSIGHT INTO TECHNOLOGICAL ASPECTS OF THE EVOLUTION OF THE HENNEBIQUE REINFORCED CONCRETE SYSTEM.....	1160
<i>J. Jasieńko, M. Moczko, A. Moczko, D. Wala, R. Dżugaj</i>	CENTENNIAL HALL IN WROCŁAW (POLAND) – UNIQUE, HUNDRED YEARS OLD CONCRETE STRUCTURE OF MAX BERG	1171
<i>I. Kirizsán, B. Szabo, I. Kirizsán</i>	CRITICAL ANALYSIS OF GOTHIC ROOF STRUCTURE CONFORMATION – THE ROLE OF THE COMPOSING ELEMENTS AND DEVICES	1180
<i>A. Koçak, B. Zengin</i>	DETERMINING MATERIAL AND FREE VIBRATION VALUES OF HISTORICAL STRUCTURES BY WAY OF SAMPLING	1189
<i>W. Laska</i>	CONCRETE – AUSTERITY, SINCERITY, BEAUTY. FAÇADE AND INTERIORS RENOVATION OF THE CENTENNIAL HALL IN WROCLAW	1205
<i>X. Laumain, Á. López Sabater</i>	ROMAN OPUS CRATICIUM, A REDISCOVERED CONSTRUCTION TECHNOLOGY.....	1213
<i>I. Lawrowska</i>	ANALYSIS OF THE TERRITORIAL LAYOUT OF BREST-LITOVSKI (XIV-XVI CENTURY)	1220
<i>M. Mosoarca, V. Gioncu, V. Fodor</i>	HISTORICAL WOOD BEARING STRUCTURES. STRUCTURAL DEFICIENCIES AND CONSOLIDATION SOLUTIONS FOR CHURCHES LOCATED IN BANAT COUNTY, ROMANIA	1231
<i>J. G. Muñoz, J. Grau Engüix, C. M. Jiménez</i>	TILE VAULTS IN CONTEMPORARY ARGENTINA	1240
<i>I. Papayianni, V. Pachta, M. Stefanidou, S. Konopissi</i>	SURVEY OF TECHNOLOGICAL CHARACTERISTICS OF STRUCTURAL MORTARS OF DIFFERENT HISTORIC PERIODS.....	1248
<i>L. Pardela, W. Czamara, D. Olearczyk, R. Stodolak</i>	HYDROTECHNICAL STRUCTURES OF WROCLAW FORTIFICATIONS.....	1255
<i>M. Philokyprou, E. Fiouri, E. Limbouri-Kozakou</i>	RUINED AND ABANDONED TRADITIONAL SETTLEMENTS. THE CASE OF CYPRUS	1264
<i>D. Roubien</i>	CONSTRUCTION TECHNIQUES IN 19TH CENTURY ATHENS AND THEIR IMPACT ON TODAY RESTORATION PROJECTS	1273
<i>A. Säbel, S. M. Holzer</i>	19TH CENTURY CURVED BOARD ROOFS IN BAVARIA	1282
<i>J. Sarrazola Martins, A. Sousa Gago, J. Caldas</i>	ROOF AND CEILING WOOD STRUCTURES IN PORTUGUESE CHURCHES FROM THE FIFTEENTH TO THE SEVENTEENTH CENTURY: CONSTRUCTIVE CHARACTERIZATION AND COMPARISON WITH THE SPANISH STRUCTURES	1293

<i>A. Soikkeli, J. Tervaoja</i>	
WORLD'S LARGEST WOODEN CHURCH IN KERIMÄKI.....	1302
<i>J. Sroczyńska</i>	
ROLE OF ICT TECHNOLOGIES IN THE CONSERVATION OF BUILDING MONUMENTS	1309
<i>R. M. Talaverano</i>	
SPANISH LATE GOTHIC FLAT RIBBED VAULTS: KEYPOINTS OF THEIR STRUCTURAL DESIGN.....	1317
<i>K.M. Tou, C.C. Lam, V.P. Iu, K.P. Kou</i>	
CAPACITY SPECTRUM STUDY OF THE RUINS OF ST. PAUL'S, MACAU	1324
<i>K. Verswijver, Q. Collette, R. De Meyer, I. Bertels, I. Wouters</i>	
CHARLES MARCELLIS AND ARTHUR VIERENDEEL: A CENTURY OF BELGIAN BRIDGE BUILDING (1835-1940)	1332
<i>D. Wendland</i>	
RESEARCH ON "CELL VAULTS": ANALYTIC AND EXPERIMENTAL STUDIES ON THE TECHNOLOGY OF LATE-GOTHIC VAULT CONSTRUCTION	1339
<i>K. Won-in, C. Khaokheiw, P. Dararutana</i>	
THERMOLUMINESCENCE DATING OF MAENAM NOI KILN, CENTRAL THAILAND	1347
<i>A. Yousefnezhad</i>	
RECOGNITION OF A HISTORICAL LIBRARY BY AN APPROACH TO CONSTRUCTION TECHNOLOGY	1351
 SEISMIC BEHAVIOR AND RETROFITTING	
<i>I. Andreeescu, M. Mosoarca</i>	
THE RECOVERED BEAUTY. RESTAURATION AND RECONVERSION OF THE ROMAN – CATHOLICCHURCH OF BOBDA, ROMANIA	1361
<i>M. Andreini, A. De Falco, M. Sassu</i>	
DAMAGE MECHANISMS IN MASONRY BUILDINGS AND PEAK GROUND ACCELERATION DURING THE 2009 EARTHQUAKE IN ABRUZZO (ITALY)	1370
<i>J. Appleton, V. Appleton, M.F. da Rocha, R. Pombo</i>	
STRUCTURAL INTERVENTION AT THE HEADQUARTERS OF BANK OF PORTUGAL	1379
<i>I. Bergamasco, B. Carpani, P. Clemente, V. Papaccio</i>	
SEISMIC PRESERVATION OF ARCHEOLOGICAL SITES: THE CASE OF POMPEI.....	1386
<i>C. Cancino, S. Lardinois</i>	
AN ARCHITECTURAL AND ENGINEERING APPROACH TO COLLECT FIELD INFORMATION FOR THE SEISMIC RETROFITTING OF HISTORIC EARTHEN BUILDINGS IN PERU.....	1395
<i>C. F. Carocci, C. Circo, M. Costa, S. Giuffrida, L. Scuderi, M. R. Vitale</i>	
A RECONSTRUCTION PLAN FOR VILLA SANT'ANGELO AND TUSSILLO (AQ). PRELIMINARY ANALYSES	1405
<i>C. F. Carocci, M. Costa</i>	
CASENTINO (AQ): A SEISMIC IMPROVEMENT PROJECT FOR MASONRY BUILDINGS.....	1414

<i>C. F. Carocci, C. Tocci</i> L'AQUILA REGION MASONRY WORKS	1423
<i>M. A. Chiorino, R. Ceravolo, C. G. Lai, C. Casalegno</i> SURVEY, SEISMIC INPUT AND STRUCTURAL MODELLING OF THE "REGINA MONTIS REGALIS" BASILICA AND LARGE ELLIPTICAL DOMEAT VICOFORTE, NORTHERN ITALY	1432
<i>P. Clemente, A. De Stefano, R. Zago</i> SEISMIC RETROFIT OF HISTORICAL BUILDINGS WITH SEISMIC ISOLATION	1441
<i>E. Coïsson, F. Ottoni</i> THE PROBLEM OF LARGE SCALE EVALUATION OF MASONRY BUILDINGS SEISMIC RISK IN DEFINING INTERVENTION PRIORITIES.....	1449
<i>A. D'Ambrisì, V. Mariani, M. Mezzi</i> NONLINEAR ANALYSIS OF A TALL HISTORICAL MASONRY TOWER.....	1457
<i>A. Di Mattia</i> SEISMIC RESPONSE ANALYSIS AND REHABILITATION PROJECT FOR A HISTORICAL MASONRY CONSTRUCTION, DAMAGED BY THE L'AQUILA EARTHQUAKE OF 06 APRIL 2009.....	1465
<i>A. Di Tommaso, R. Lancellotta, F. Focacci, F. Romaro</i> SEISMIC STABILITY EVALUATION OF THE GHIRLANDINA TOWER IN MODENA, ITALY	1474
<i>M. Drdácký, S. Urushadze, M. Wünsche</i> RETROFITTING OF IMPERFECT CARPENTRY JOINTS FOR INCREASED SEISMIC RESISTANCE	1485
<i>B. Faggiano, A. Formisano, D. De Gregorio, T. De Lucia, F. M. Mazzolani</i> THE STRUCTURAL BEHAVIOUR ASSESSMENT OF GOLDEN MILES VESUVIAN VILLAS THROUGH A SEISMIC-VOLCANIC QUICK PROCEDURE	1493
<i>L. Ferrario, A. Marini, V. Andreis, S. Zanotti, P. Riva, E. Giuriani</i> BEHAVIOUR AND RETROFITTING OF SINGLE-LEAF VAULTS UNDER DISTRIBUTED HORIZONTAL FORCES	1503
<i>C. Fonseca Ferreira, D. D'Ayala</i> NUMERICAL MODELLING AND STRUCTURAL ANALYSIS OF ECCLESIASTICAL BUILDINGS IN PERU FOR SEISMIC RETROFITTING	1512
<i>A. Formisano, G. Florio, R. Landolfo, L. Krstevska, L. Tashkov</i> EXPERIMENTAL AND NUMERICAL INVESTIGATION ON A MONUMENTAL MASONRY BUILDING DAMAGED BY THE ABRUZZO EARTHQUAKE	1520
<i>A. Formisano, F. M. Mazzolani</i> COMPARISON AMONG ANALYSIS METHODOLOGIES FOR SEISMIC VULNERABILITY ASSESSMENT OF MASONRY SCHOOL BUILDINGS IN TORRE DEL GRECO	1529
<i>M. Golabchi, M. Khoramirouz</i> STRUCTURAL MODELING OF DOUBLE-SHELL DOME OF IMAM MOSQUE (ISFAHAN) AND SEISMIC MODEL ANALYSIS	1538
<i>O. Gunes, B. Gunes, I. Sozenoglu</i> PERFORMANCE-BASED SEISMIC EVALUATION AND RETROFITTING OF HISTORIC UNREINFORCED CONCRETE WALL BUILDINGS WITH INTERIOR STEEL FRAMES	1546

<i>M. Hejazi, H. Mehdad, B. Hejazi</i>	
SEISMIC STUDY AND RESTORATION PLAN OF ADOBE TOWER NO. 32 IN THE BAM CITADEL, IRAN	1556
<i>M. Hodjat, S. Asadi</i>	
INTRODUCTION ON IRAN EARTHQUAKE DAMAGED HISTORICAL SITES	1565
<i>P. Homami, M. Golabchi, M. J. Jabbarzadeh</i>	
SEISMIC VULNERABILITY ASSESSMENT AND REHABILITATION DESIGN OF NAGHAREH-KHANEH EDIFICE	1573
<i>A. Javani Dizaji</i>	
BEHAVIOR OF IRANIAN ARCHES IN EARTHQUAKE.....	1582
<i>L. Karapitta, Ch. Mouzakis, Ch.-E. Adami, E. Vintzileou</i>	
NON LINEAR SEISMIC RESPONSE OF THREE-LEAF MASONRY STRUCTURES	1590
<i>A. Koçak, B. Zengin</i>	
OBSERVED SEISMIC DAMAGES OF HISTORICAL STRUCTURES WHICH ARE LOCATED IN MARMARA REGION IN TURKEY AND MECHANICAL PROPERTIES OF STRUCTURES	1599
<i>F. Lorenzoni, T. Aoki, F. Casarin, C. Modena, F. da Porto, D. Sabia, V. Sumini</i>	
POST-EARTHQUAKE ASSESSMENT OF THE CIVIC TOWER IN L'AQUILA: AMBIENT VIBRATION TESTS AND STRUCTURAL HEALTH MONITORING	1612
<i>G. Magenes, A. Penna, M. Rota, A. Galasco, I. Senaldi</i>	
SHAKING TABLE TEST OF A STRENGTHENED FULL SCALE STONE MASONRY BUILDING WITH FLEXIBLE DIAPHRAGMS	1621
<i>C. A. Monguilner, S. B. Aladro, M. E. Castro</i>	
SEISMIC ASSESSMENT OF THE HERITAGE BUILDING IN SAN JUAN CITY – ARGENTINA.....	1630
<i>S. Moreira, L. F. Ramos, D. V. Oliveira, R. P. Fernandes, J. Guerreiro, P. B. Lourenço</i>	
EXPERIMENTAL SEISMIC BEHAVIOUR OF WALL-TO-HALF-TIMBERED WALL CONNECTIONS	1639
<i>M. Mosoarca</i>	
INNOVATIVE SYSTEM FOR CONSOLIDATION OF HISTORICAL FEW STOREY MASONRY BUILDINGS SITUATED IN SEISMIC AREAS.....	1647
<i>M. Mosoarca, V. Gioncu</i>	
FAILURE MECHANISMS OF ORTHODOX CHURCHES SITUATED IN SEISMIC AREAS IN ROMANIA	1656
<i>Ch. Mouzakis, Ch.-E. Adami, L. Karapitta, E. Vintzileou</i>	
SEISMIC BEHAVIOUR OF A REHABILITATED CROSS VAULT.....	1665
<i>M. Palmieri, G. Magenes, C. G. Lai, A. Penna, F. Bozzoni, M. Rota, G. Macchi, F. Auricchio, M. D. Mangriots, A. Menon, A. Meher Prasad, C. V. R. Murty</i>	
REDUCTION OF SEISMIC RISK OF ROMAN AND HINDU TEMPLES	1674
<i>F. Parisi, N. Augenti</i>	
MULTI-RISK ASSESSMENT OF A CULTURAL HERITAGE MASONRY BUILDING SUBJECTED TO BOTH EARTHQUAKE AND VOLCANIC THREATS.....	1682
<i>M. A. Parisi, C. Chesi, C. Tardini, F. Altamura</i>	
SEISMIC STRENGTHENING OF TIMBER ROOF STRUCTURES: A CASE STUDY	1691

<i>N. Quinn, D. D'Ayala, D. Moore</i>	
EXPERIMENTAL TESTING AND NUMERICAL ANALYSIS OF QUINCHA UNDER LATERAL LOADING	1699
<i>L. Shengcai, L. Yu, Y. Jianli</i>	
PARAMETERS FITTING ON THE DYNAMIC BEHAVIOURS OF AN ANCIENT PAGODA DAMAGED BY WENCHUAN EARTHQUAKE	1709
<i>L. Sorrentino, L. Ronchetti, E. Raglione, D. Liberatore</i>	
STRUCTURAL ANALYSIS OF EARTHQUAKE-RESISTANT HISTORICAL DETAILS OF L'AQUILA (CENTRAL ITALY) BUILDINGS.....	1716
<i>D. Torrealva, E. Vicente</i>	
EXPERIMENTAL EVALUATION OF SEISMIC BEHAVIOUR OF QUINCHA WALLS FROM THE HISTORICAL CENTRE OF LIMA – PERU	1724
<i>A. Vefa Orhon</i>	
RETROFIT TO PRESERVE: REVIEW OF SEISMIC RETROFITTING METHODS FOR HISTORICAL URM BUILDINGS.....	1731
<i>S. Toker Beeson, C. Ozmen, A. Ihsan Unay</i>	
TEMPORARY IMMEDIATE STEEL BUTTRESSING THE DAMAGED HISTORICAL STRUCTURES AFTER EARTHQUAKES	1739
 REHABILITATION OF MASONRY STRUCTURES	
<i>M. Acito, G. Milani</i>	
SAFETY ASSESSMENT OF AN ANCIENT MASONRY STRUCTURE BY MEANS OF A HOMOGENIZED NON-LINEAR APPROACH.....	1747
<i>M. Andreini, A. De Falco, M. Sassu</i>	
ON SITE TESTS FOR THE MECHANICAL CHARACTERIZATION OF MASONRY WALLS WITH CHAOTIC TEXTURE	1755
<i>L. G. Baltazar , F. M. A. Henriques, F. Jorne</i>	
HYDRAULIC LIME GROUTS FOR MASONRY INJECTION – EFFECTS OF ADMIXTURES ON THE FRESH GROUT PROPERTIES	1763
<i>A. Borri, G. Castori, M. Corradi</i>	
MASONRY CONFINEMENT WITH SRP COMPOSITES	1771
<i>G. Brandonisio, A. De Luca, E. Mele, G. M. Montuori</i>	
MULTI-STORY MASONRY BUILDINGS: EVALUATION OF EFFECTIVENESS OF MECHANICAL STRENGTHENING.....	1780
<i>M. Bruggi, G. Milani, A. Taliercio</i>	
DESIGN OF THE OPTIMAL FIBER REINFORCEMENT FOR MASONRY STRUCTURES VIA TOPOLOGY OPTIMIZATION.....	1789
<i>D. Covatariu, M. Budescu</i>	
INVESTIGATION ON ADHERENCE CHARACTERISTICS OF LOW-STRENGTH MORTARS USED IN THE DAMAGED HISTORICAL MASONRY STRUCTURES	1797
<i>G. Dmochowski, P. Berkowski, J. Szołomicki, M. Y. Minch</i>	
STRENGTHENING OF THE OVERLOADED MASONRY WALL OF HISTORICAL SERVICE BUILDING.....	1804

<i>A. Formisano, R. Fonti, F. M. Mazzolani</i>	
THE HISTORICAL CENTRE OF POGGIO PICENZE	
AFTER L'AQUILA EARTHQUAKE:	
BEHAVIOUR AND STRENGTHENING OF MASONRY AGGREGATE WALLS	1811
<i>E. Garbin, M. Panizza, M. R. Valluzzi, C. Modena</i>	
A SIMPLIFIED MODEL TO ESTIMATE THE CONTRIBUTION OF EB-FRP	
TO THE SHEAR STRENGTH OF MASONRY PANELS	1819
<i>V. Giamundo, G. P. Lignola, A. Prota, G. Manfredi</i>	
DIAGONAL STRENGTH OF ADOBE BRICK WALL.....	1827
<i>A. A. Hamid, M. Orphy</i>	
DURABILITY OF HISTORIC BRICK MASONRY	1836
<i>D. W. Harvey Jr., M. P. Schuller, W. T. Ruth</i>	
INTERNAL STRENGTHENING OF HISTORIC CLAY BRICK MASONRY	
PUMP HOUSES IN NEW ORLEANS.....	1844
<i>J. Jasieńko, Ł. Bednarz, M. Rutkowski, T. Nowak</i>	
STATIC ANALYSIS, STRENGTHENING AND MONITORING OF HISTORIC	
ST. ANN'S CHURCH IN ZĄBKOWICE ŚLĄSKIE (POLAND)	1852
<i>A. Kwiecień, B. Zajac</i>	
ENERGY APPROACH IN ANALYSIS OF MASONRY COLUMNS CONFINED	
WITH GFRP MESH BONDED ON STIFF AND FLEXIBLE ADHESIVES	1864
<i>A. Mauro, G. de Felice</i>	
SEISMIC ASSESSMENT OF MULTI-LEAF MASONRY STRENGTHEN	
WITH INJECTIONS OR TRANSVERSAL TIES	1873
<i>M.Y. Minch, J. Szołomicki, P. Berkowski, G. Dmochowski</i>	
STRENGTHENING OF BAROQUE MONASTERY IN GŁĘBOWICE, POLAND	1880
<i>Y. Ouyang, R. Wang, X. Yang, N.K. Liu, X.L. Gu</i>	
MECHANICAL ANALYSIS FOR HISTORICAL MASONRY WALLS STRENGTHENED	
BY REINFORCED CONCRETE LAYER AND STEEL FRAMES.....	1888
<i>I. Papayianni, V. Pachta</i>	
HIGH PERFORMANCE LIME BASED GROUTS FOR REPAIR OF HISTORIC	
MASONRIES	1897
<i>E. Quagliarini, F. Monni, S. Lenci</i>	
MASONRY STRENGHTENING THROUGH BASALT FIBRE ROPES.	
EXPERIMENTAL AND ANALYTICAL RESULTS	1905
<i>E. Rodríguez-Mayorga, E. Yanes, A. Sáez</i>	
THE RESTORATION OF THE PARISH CHURCH OF SAN DIONISIO	
IN JEREZ DE LA FRONTERA (SPAIN).....	1914
<i>V. Russo, M. De Gennaro, P. Cappelletti, G. Ceniccola</i>	
THE BELL TOWER OF THE BASILICA OF SAINT AUGUSTINE MAYOR	
IN NAPLES (ITALY): INTERDISCIPLINARY RESEARCHES	
FOR THE CONSERVATION OF AN ARCHITECTURE AT RISK.....	1922
<i>B. Silva, E. Pigouni, M. R. Valluzzi, F. da Porto, C. Modena</i>	
ASSESSMENT OF THE EFFECTIVENESS OF GROUT INJECTION	
ON THE CONSOLIDATION OF 3-LEAF STONE MASONRY WALLS	
THROUGH THE USE OF NDT AND DT	1931

<i>F. Silveri, G. Profeta, P. Riva, C. Algeri, E. Bolognini, E. Poverello , P. Panzeri</i>	
PRE STRESSED VERTICAL INJECTED ANCHORS ON HISTORICAL MASONRY:	
A CASE STUDY, THE BELL TOWER OF BOTTA DI SOTTO IL MONTE	
PAPA GIOVANNI XXIII	1940
<i>A. Varatharajan, S. Vignesh, C.S. Prashanth, A. Menon</i>	
STRUCTURAL ASSESSMENT AND STRENGTHENING OF MULTI-TIERED	
MASONRY TOWERS.....	1949
<i>M. Wünsche, S. Urushadze, S. Pospišil, S. Hračov</i>	
CYCLIC BEHAVIOUR OF THE ADOBE BRICK WALLS BEFORE	
AND AFTER THE REINFORCEMENT	1958
AUTHOR INDEX	XXXIII

Volume 3

REHABILITATION OF TIMBER STRUCTURES

<i>J. Appleton, V. Appleton, A. Aquino, M. F. da Rocha</i>	
LIBRARY ROOF – SANTA MARIA DE ALCOBACA ABBEY, ALCOBACA, PORTUGAL	1969
<i>D. Bajno</i>	
THE DURABILITY AND SAFE USE OF SELECTED WOODEN STRUCTURES	
BASED ON THE EXAMPLE OF THE SEVENTEENTH CENTURY CASTLE TOWER	
IN BIERUTÓW, LOWER SILESIA PROVINCE, POLAND	1978
<i>D. T. Biggs, J. A. Null</i>	
STRENGTHENING AN ADIRONDACK HIPPED ROOF	1984
<i>I. Burawska, A. Rozanska, A. Jankowska, P. Beer</i>	
TECHNICAL STATE ANALYSIS AND REINFORCEMENT PROJECT	
OF ANTIQUE WOODEN FLOORING WITH JOIST STRUCTURE.....	1992
<i>I. Burawska, A. Tomusiak, M. Zbieć, P. Beer</i>	
REDUCING THE IMPACT OF KNOTS ON THE STATIC WORK OF BENT	
WOODEN BEAMS BY LOCAL REINFORCEMENT WITH CFRP STRIP	1998
<i>C. Ceraldi, M. Lippiello, E. Russo Ermolli</i>	
TIMBER PINS CONNECTIONS: RELIABILITY OF BOLTED JOINTS DESIGN RULES	2004
<i>L. Debailleux</i>	
INDEXING SYSTEM FOR TRADITIONAL WOODEN FRAME STRUCTURE	
RECOGNITION	2013
<i>E. Decher, C. Lanivschi</i>	
TIMBER STRUCTURES REPAIR WITH WFRP (WOOD FIBRES REINFORCED	
POLYESTER).....	2020
<i>I. Giongo, M. Piazza, R. Tomasi</i>	
CAMBERING OF TIMBER COMPOSITE BEAMS BY MEANS OF SCREW FASTENERS.....	2029
<i>M. Kloiber, J. Tippner, V. Hermánková, J. Štainerbruch</i>	
COMPARISON OF RESULTS OF MEASURING BY CURRENT NDT METHODS	
WITH RESULTS OBTAINED THROUGH A NEW DEVICE FOR WOOD	
MECHANICAL RESISTANCE MEASURING	2035

<i>C. Miedziałowski, M. Malesza</i>	
ANALYSIS OF FORMATION AND STATIC BEHAVIOR OF TIMBER ROOF STRUCTURES IN RELIGION HISTORICAL BUILDING.....	2044
<i>E. Poletti, G. Vasconcelos</i>	
SEISMIC BEHAVIOUR OF TRADITIONAL HALF-TIMBERED WALLS: CYCLIC TESTS AND STRENGTHENING SOLUTIONS	2051
<i>S. Sánchez-Beitia, L. Torres, J. Barrallo, B. Iraola</i>	
THE HOLE DRILLING TECHNIQUE ON TIMBER STRUCTURES: PREVIOUS TESTS.....	2060
<i>E. Sierow, A. Sierow, R. Orłowicz</i>	
PROBLEMS INVOLVED IN REPAIRING TIMBER CHURCH BUILDINGS IN NORTHERN RUSSIA.....	2065
<i>H. S. Sousa, J. M. Branco, P. B. Lourenço</i>	
CHARACTERIZATION OF OLD CHESTNUT BEAMS SECTIONS WEAKENED BY DECAY	2070
<i>H. S. Sousa, J. M. Branco, P. B Lourenço</i>	
ASSESSMENT OF STRENGTH AND STIFFNESS VARIATION WITHIN OLD TIMBER BEAMS.....	2079
<i>F. Vegas, C. Mileto, A. Alonso, A. Martínez</i>	
AUTOBIOGRAPHY OF A BEAM	2088
<i>E. Zamperini</i>	
AXIOLOGICAL APPROACH TO STRENGTHENING OF TIMBER LOAD BEARING FLOOR STRUCTURES	2097
<i>Chun Qing, Zhan Yang, Pan Jianwu</i>	
EXPERIMENTAL STUDY ON FLEXURAL BEHAVIOR OF TIMBER BEAMS REINFORCED WITH NEARSURFACE MOUNTED CFRP PLATES.....	2106
<i>Weiping Zhang, Xiaobin Song, Qinghua Huang, Xianglin Gu, Yunchao Zhang</i>	
ON-SITE TESTING AND EVALUATION OF A RELOCATED AND RECONSTRUCTED HISTORICAL TIMBER BUILDING.....	2112
 REHABILITATION OF BRIDGES	
<i>L. Bednarz, A. Kasiedczak, R. Stachańczyk, A. Roscher</i>	
CONSERVATION RENOVATIONS OF THE BRIDGES IN THE MUSKAU PARK.....	2121
<i>A. Čaušević, L. Kudumović, N. Rustempašić, N. Kuljuh</i>	
SUSTAINABLE REHABILITATION, PRESERVATION AND PROTECTION OF ACCESS ARCH STONE BRIDGE AT THE ENTRANCE TO THE MEDIEVAL OLD TOWN KORČULA	2132
<i>B. T. de Oliveira</i>	
RESTORATION OF THE BRIDGES OF OURO PRETO, MG, BRAZIL.....	2139
<i>S. De Santis, G. de Felice, D. Peluso</i>	
AN OVERVIEW ON ITALIAN RAILWAY MASONRY BRIDGES WITH LOAD-CARRYING CAPABILITY ESTIMATE	2145
<i>J. M. Dulińska</i>	
EVALUATION OF DYNAMIC RESPONSE OF STONE BRIDGE TO ASYNCHRONOUS SEISMIC EXCITATION	2154

<i>N. Domède, T. Stablon, A. Sellier</i>	
MECHANICAL ANALYSIS OF AN OLD MASONRY BRIDGE IN PARIS	2162
<i>R. Ferrari, G. Cucchetti, E. Rizzi</i>	
ELASTOPLASTIC STRUCTURAL ANALYSIS OF THE PADERNO D'ADDA BRIDGE (ITALY, 1889) BASED ON LIMIT ANALYSIS	2171
<i>M. Mehdianpour, T. Eisenkolb</i>	
EXPERIMENTAL INVESTIGATIONS ON SLIDING FRICTION OF HISTORIC BRIDGE BEARINGS.....	2181
<i>M.J.C Morais, G.A.F. Rouxinol, P. J. R. Pimenta</i>	
ASSESSMENT OF THE CAPACITY OF MONDIM DA BEIRA BRIDGE USING TWO DISTINCT MESH GENERATIONS.....	2189
<i>M. Paradiso, G. Tempesta, S. Galassi, D. Zerboni</i>	
THE ANCIENT BRIDGE ROMAJOLO IN BAGNO A RIPOLI (FI): FROM THE RECENT DISCOVERY TO THE REHABILITATION PROJECT	2196
<i>A. Saisi, C. Gentile</i>	
MONITORING AND FE MODELING OF A HISTORIC IRON BRIDGE.....	2205
<i>J. Sena-Cruz, J. C. Araújo, F. Castro, M. Jorge</i>	
ASSESSMENT OF THE BOCO HISTORICAL RC BRIDGE	2214
<i>J. Sena-Cruz, R. M. Ferreira, L. Ramos, F. Fernandes, T. Miranda, F. Castro</i>	
ASSESSMENT OF THE LUIZ BANDEIRA HISTORICAL BRIDGE	2222
<i>S. Sire, L. Gallegos Mayorga, J-L. Martin, C. Doudard, S. Calloch</i>	
FAST CHARACTERIZATION OF FATIGUE PROPERTIES OF A FRENCH HISTORICAL RAILWAY BRIDGE PUDDLE IRON	2231
<i>C. Tardini, C. Chesi</i>	
A NEW CONCEPT IN BRIDGE DESIGN IN THE 19TH CENTURY: ITHIEL TOWN'S TIMBER BRIDGES	2238
<i>K. Veihelmann, S. Holzer</i>	
EARLY CONCRETE BRIDGES WITHOUT REINFORCEMENT.....	2245
<i>V. Wetzk</i>	
HISTORIC BRIDGE BEARINGS – IDENTIFYING MATERIAL CHARACTERISTICS: COMPRESSION TEST	2251
<i>Wang Enyong, Cui Jianbo, Wu Di, Zhang Zhibin, Hu Yuxia, Wei Suping, Tian Yunxia</i>	
DIGITIZATION OF ANCIENT BRIDGES IN GANSU	2258
<i>Geun Chang Cha, Jong Ku Lee, Young Sin Park, Ho Soo Kim</i>	
STRUCTURAL BEHAVIOR CHARACTERISTICS OF ARCHED STONE BRIDGE ACCORDING TO FOUNDATION AND FILLER TYPE.....	2264

MONITORING, DIAGNOSIS AND LASER SCANNING

<i>N. Alcantara, L. F. Ramos, P. Mendes, J. Ferreira, F. Fernandes, P. B. Lourenço</i>	
FINITE ELEMENT SIMULATIONS FOR THE COMPREHENSION OF PHYSICAL PHENOMENA INVOLVED IN ELECTRIC IMPEDANCE TOMOGRAPHY OF MASONRY STRUCTURES	2271

<i>C. Bertolini-Cestari, S. Invernizzi, A. Spanò, L. Mallamaci</i>	
LASER MODELING AND STRUCTURAL ASSESSMENT OF A XVIITH CENTURY	
WOODEN DOME	2280
<i>G. Bitelli, C. Colla, E. Gabrielli, F. Girardi, F. Ubertini</i>	
QUANTITATIVE MONITORING OF SUPERFICIAL DECAY EVOLUTION	
IN PLASTERED AND UNPLASTERED OUTDOORS MASONRY	2288
<i>G. Boscato, S. Russo, F. Sciarretta</i>	
THE DOUBLE-LAYERED FAÇADES OF PALAZZO DUCALE IN VENICE:	
RESULTS FROM TESTING AND LONG-TERM MONITORING	2297
<i>A. Bossio, M. Montuori, F. Bellucci, G.P. Lignola, A. Prota, E. Cosenza, G. Manfredi</i>	
INDIRECT MEASURE OF CORROSION LEVEL BASED ON CRACK OPENING	2305
<i>G. Buda, M. Galizia, A. Lo Presti, F. Privitera, G. Randazzo, C. Santagati, M. Santagati</i>	
INTERDISCIPLINARY INVESTIGATIONS AIMED AT THE PRESERVATION	
OF A FUNERARY ROMAN MONUMENT NAMED “TORRE ROSSA”	
IN FIUMEFREDDO DI SICILIA.....	2314
<i>P. Călin Răcătăianu, A. Mihăilă</i>	
NEW DATABASE MAPPING SYSTEM (NDMS) – A NON-DESTRUCTIVE METHOD	
OF BUILDING STONES’ ANALYSIS	2323
<i>G. Cardani, L. Binda, F. da Porto, F. Casarin, M. Dalla Benetta, A. Donadio, S. Tonna</i>	
THE ROLE OF THE MASONRY QUALITY EVALUATION IN HISTORIC	
CONSTRUCTIONS: THE CASE OF ST. PAUL HOSPITAL OF SAVONA, ITALY	2331
<i>A. Carpinteri, S. Invernizzi, G. Lacidogna, F. Accornero</i>	
ACOUSTIC EMISSION MONITORING OF FRESCOS DEGRADATION	
IN A XVIIth CENTURY CHAPEL OF THE “SACRED MOUNTAIN OF VARALLO”	
(ITALY).....	2340
<i>F. Casarin, M. Humo, F. Lorenzoni, F. da Porto, P. Girardello, C. Modena, L. Cantini, S. Kulukcija</i>	
EXPERIMENTAL INVESTIGATIONS ON TWO TRADITIONAL STONE	
MASONRY MINARETS IN BOSNIA AND HERZEGOVINA.....	2349
<i>F. Casarin, C. Modena, E. Bello, F. da Porto, F. Lorenzoni, P. Girardello, S. Menon</i>	
STRUCTURAL HEALTH MONITORING OF THE ROMAN ARENA	
OF VERONA, ITALY	2358
<i>C. Colla, V. Rajcic, E. Gabrielli, A. Juez Fernandes, F. Bastianini, A. Largo,</i>	
<i>F. Gruener, M. Krueger, F. Lehmann, E. Esposito, H. Maraqa, S. Al-Janazreh,</i>	
<i>G. Castellazzi, C. Gentilini, G. Pascale, F. Ubertini</i>	
INTEGRATED APPROACH FOR ON-SITE ASSESSMENT OF CONSERVATION	
STATE OF A HISTORICAL MASONRY BUILDING: MALVEZZI PALACE, ITALY	2367
<i>A. Elyamani, J.O. Caselles, J. Clapes, P. Roca</i>	
ASSESSMENT OF DYNAMIC BEHAVIOR OF MALLORCA CATHEDRAL.....	2376
<i>H. Fereshteh</i>	
DIGITAL TECHNOLOGIES IN DOCUMENTING THE CULTURAL HERITAGE	
REVIEW OF LASER SCANNERS	2385
<i>C. Gentile, A. Saisi, A. Cabboi</i>	
DYNAMIC MONITORING OF A MASONRY TOWER	2390
<i>J. Grosel, W. Sawicki, Z. Wójcicki</i>	
VIBRATION MEASUREMENTS IN ANALYSIS OF HISTORICAL STRUCTURES.....	2398

<i>S. Gunay</i>	
STRUCTURAL AND MATERIAL ANALYSIS OF HISTORIC BUILDINGS IN A GIS BASED URBAN CONSERVATION PROJECT.....	2412
<i>S. Hanazato, T. Hanazato, Y. Uekita, K. Sato, K. Nitto, K. Ono, S. Yoyok, P. Diananta, E. Pradipto, A. Nakatani</i>	
STRUCTURAL CHARACTERISTIC OF TRADITIONAL WOODEN HOUSES IN SOUTH NIAS, INDONESIA	2418
<i>D. Jayanthi , R. Vedamuthu</i>	
INVESTIGATION OF THE STATUS OF THE DETERIORATION OF A SANDSTONE MONUMENT AT KANCHIPURAM, TAMILNADU, INDIA BY DECAY MAPPING	2425
<i>T. Kruglowa, R. Kliger</i>	
NON-DESTRUCTIVE INVESTIGATION OF MATERIAL PROPERTIES OF THE VASA WARSHIP: A PILOT STUDY	2432
<i>A. Kwiecień, J. Chelmecki, P. Matysek</i>	
NON-DESTRUCTIVE TEST OF BRICK COLUMNS USING CHANGE IN FREQUENCY AND INERTANCY RESPONSE	2437
<i>E. C. Manning, L. F. Ramos, F. Fernandes, C. Sousa, M. Azenha</i>	
TUBE-JACK TESTING FOR IRREGULAR MASONRY: PRELIMINARY TESTING	2445
<i>N. Masini, D. Liberatore, F. Gizzi, G. Leucci, G. Quarta, R. Persico</i>	
ANALYSIS OF DAMAGE AND DIAGNOSTIC INVESTIGATIONS ON TRICARICO CATHEDRAL (ITALY).....	2454
<i>L. Mateus, N. Brito, V. Ferreira, M. Barbosa, J. Aguiar</i>	
NEW TOOLS FOR VISUAL ASSESSMENT OF BUILDING DEFORMATIONS	2463
<i>P. Matysek, D. Łątka</i>	
COMMENTS ON THE APPLICATION OF THE SCELEROMETRIC METHOD IN THE DIAGNOSTIC OF BRICK MASONRY	2471
<i>J. McInerney, I. Trzcinski, M. J. DeJong</i>	
DISCRETE ELEMENT MODELLING OF MASONRY USING LASER SCANNING DATA.....	2480
<i>A. M. Metheniti, A. Kalinyktakis, A. Georgopoulos</i>	
TERRESTRIAL LASER SCANNING FOR MONITORING A HISTORIC BYZANTINE CHURCH	2488
<i>L. Mollo, R. Agliata, C. Giudicianni</i>	
SMAS FOR STRUCTURAL RESPONSE CONTROL, A SHORT REVIEW	2497
<i>M. Riggio, A. Sandak, J. Sandak</i>	
IN-SITU ASSESSMENT OF STRUCTURAL TIMBER USING SELECTED WAVE-BASED NDT METHODS.....	2504
<i>K. Stala</i>	
NON-DESTRUCTIVE TECHNOLOGIES AS A TOOL FOR ARCHAEOLOGIST AND HISTORIAN OF ARCHITECTURE IN THE STUDIES AND RESEARCH OF THE INSTITUTE OF HISTORY OF ARCHITECTURE AND MONUMENT PRESERVATION OF CRACOW UNIVERSITY OF TECHNOLOGY	2513
<i>C. Thelin, F. Höst, C. Rosenberg</i>	
ANALYSIS OF HISTORIC MASONRY STRUCTURES SUPPORTED BY 3D LASER SCANNING	2519

<i>C. Tiraboschi, M. Cucchi, M. Antico, L. Binda</i>	
OPTICAL SYSTEM FOR REAL-TIME MEASUREMENT OF THE ABSOLUTE DISPLACEMENTS APPLIED TO FLAT JACK TEST.....	2528
<i>E.-E. Toumbakari, D. Egglezos</i>	
IN-SITU TESTS ON THE INTERNAL WESTERN COLUMNS OF THE PARTHENON AND MODELING OF THE JOINTS' MECHANICAL PROPERTIES	2536
<i>M. Uranjek, R. Žarnić, V. Bokan-Bosiljkov, V. Bosiljkov</i>	
PERFORMANCE OF NDT, MDT AND DT TECHNIQUES IN ASSESSING THE EFFECTIVENESS OF GROUTING	2544
<i>T. Van Mele, J. McInerney, M. J. DeJong, P. Block</i>	
PHYSICAL AND COMPUTATIONAL DISCRETE MODELLING OF MASONRY VAULT COLLAPSE	2552
<i>M. Vatan, K. Kaptan</i>	
RISK MAP OF HISTORICAL HERITAGE IN TURKEY	2561
<i>A. Verdonck, M. Deceuninck</i>	
UNRAVELING AN UNIQUE CONSTRUCTION HISTORY AS A RESULT OF MONITORING: THE MEDIEVAL GATEWAY OF THE HUYSMANS FARM (EEKLO, BELGIUM).....	2567
<i>E. Verstrynghe, S. Konings, M. Wevers</i>	
THE INFLUENCE OF MOISTURE ON CREEPBEHAVIOUR OF SANDSTONE ASSESSED BY MEANS OF ACOUSTIC EMISSION	2573
<i>M. Wilińska, M. Kędzierski, R. Zapłata, A. Fryśkowska, P. Deliś</i>	
NONINVASIVE METHODS OF DETERMINING HISTORICAL OBJECTS DEFORMATION USING TLS.....	2582
 <i>MODERNIZATION AND RE-USE OF CULTURAL HERITAGE BUILDINGS</i>	
<i>M. Altin</i>	
A CRITICAL REVIEW OF PV PANEL USAGE IN THE RETROFIT OF HISTORICAL BUILDINGS	2591
<i>I. Andreeescu, M. Mosoarca</i>	
URBAN COMPLEX RENEWAL OF THE HISTORIC CITY OF CIACOVA, ROMANIA.....	2597
<i>N. Balcerzak, A. Taraszkiewicz</i>	
REVITALIZATION OF THE HISTORIC EX BREWERY AREAS IN POLAND	2605
<i>M. Beckh</i>	
TAA DZONG OF TRONGSA – REFLECTION ON THE RE-USE OF A BHUTANESE WATCHTOWER.....	2613
<i>C. Bocan</i>	
A POSSIBLE LARGE-SCALE REHABILITATION SOLUTION FOR PREFABRICATED CONCRETE PANEL BLOCKS.....	2619
<i>T. Canitez, I. Salih Canitez</i>	
AN EXAMPLE FOR THE RE-USE OF THE HISTORIC BUILDINGS FOR CONTINUITY OF CULTURAL INHERITANCE : EDIRNE BAYEZID II COMPLEX	2627

<i>A. Čaušević, L. Kudumović, N. Rustempašić, N. Kuljuh</i>	
ARCHITECTURAL RESTORATION IN SLOW TERMS, EMERGENCY AND RECOVERY SLOW: THE CASE OF POST-WAR IN SARAJEVO	2635
<i>G. Dmochowski, P. Berkowski, J. Dudkiewicz</i>	
ADAPTATION OF EARLY HERITAGE MASONRY BUILDINGS TO NEW SOCIAL ASSISTANCE FUNCTIONS	2642
<i>M. C. Forlani, D. Radogna, A. Viskovic</i>	
WOODEN FRAMED STRUCTURES FOR MASONRY BUILDINGS RETROFITTING. A PILOT PROJECT IN CAPORCIANO.....	2650
<i>P. Gerber</i>	
PROBLEMS OF MODERNISATION OF HISTORIC HOSPITALS IN LOWER SILESIA	2658
<i>M. Golež, T. Pazlar</i>	
RECYCLING HISTORIC PLASTERS FOR MORE EFFICIENT RENOVATION OF CULTURAL HERITAGE STRUCTURES	2664
<i>N. Güzel</i>	
STRUCTURAL SOLUTIONS FOR THE HISTORICAL BUILDINGS	2671
<i>K. Kuśnierz, D. Kuśnierz-Krupa</i>	
REVALORIZACJA OF THE TOWN HALL IN SIENIAWA	2680
<i>D. Lazarus</i>	
ENABLING A FUTURE FOR CULTURAL HERITAGE BUILDINGS	2687
<i>M. Morandotti, D. Besana, V. Cinieri</i>	
ENERGY IMPROVEMENT IN CULTURAL HERITAGE	2695
<i>S. Niederhagemann</i>	
MODIFICATION OF A LISTED PIT HEAD INTO A VIEWING PLATFORM.....	2702
<i>N. Olgun</i>	
SÜLEYMANİYE MOSQUE 2007-2010 RESTORATION WORKS INTERVENTION DECISIONS AND THE RESTORARTION AND STRUCTURAL STRENGTHENING OF THE MAIN DOME	2708
<i>F. L. Oliveira, C. Paim</i>	
PROPOSAL OF RESTORATION AND MAINTENANCE FOR THE COPAN BUILDING FAÇADES	2717
<i>A. Osman</i>	
REVITALIZATION OF HISTORICAL EARTHEN STRUCTURES FOR MODERN USE.....	2726
<i>R. Özakin, A. Erdem</i>	
A PALACE HAMMAM IN TURKEY: THE KUM KASRI HAMMAM.....	2735
<i>M. Panahi, N. Shiasi</i>	
THE MANNER OF REHABILITATION OF HISTORICAL VERNACULAR GARDENS (CASE STUDY IS ALI ABAD GARDEN IN BOJNOURD-IRAN)	2744
<i>A. Radivojević, M. Roter-Blagojević, A. Rajčić</i>	
PRESERVATION OF VERNACULAR ARHITECTURE IN SERBIA – AUTHENTICITY VERSUS THERMAL COMFORT ISSUES.....	2750

<i>R. Radoslav, M. Mosoarca, A.-M. Branea, M. Stelian Gaman</i>	
CONSERVATION AND RE-USE OF HISTORICAL INDUSTRIAL BUILDINGS, CASE STUDY FABRIC NEIGHBORHOOD, TIMISOARA.....	2760
<i>L. Roșiu, S. Bica</i>	
THE REUSE OF INDUSTRIAL BUILDINGS, AN EMERGENCY FOR THE PATRIMONY PROTECTION IN THE BANAT REGION OF ROMANIA.....	2769
<i>S. Sanyal</i>	
CHANGING PARADIGMS IN STRUCTURAL CONSERVATION: A CENTURY OF INTERVENTIONS IN THE SUN TEMPLE, KONARAK	2776
<i>N. Shiasi, M. Panahi</i>	
STUDY THE EFFECT OF CHANGE THE FUNCTION AFTER RESTORATION OF QAJARIE NAVAB BATH IN TEHRAN.....	2785
<i>J. Silva Pavan, R. T. M. Ribeiro</i>	
THE REUSE AS A FACTOR FOR THE HERITAGE BUILDINGS CONSERVATION IN RIO DE JANEIRO DOWNTOWN	2792
<i>M. Tanaç Zeren</i>	
UNDERSTANDING AND RE-USING THE CULTURAL HERITAGE BUILDINGS.....	2800
<i>J. Urbanik</i>	
RENOVATION OF MODERN MOVEMENT BUILDINGS, ORIGINAL FORM VERSUS BUILDING TECHNOLOGY, FROM LE CORBUSIER TO HANS SCHAROUN.....	2809
<i>A. Vefa Orhon</i>	
COMBINING AUTHENTICITY WITH MODERN: RENOVATION OF AN ART NOUVEAU BUILDING IN ISTANBUL.....	2818
<i>M. E. Yakartepe, A. B. Gokarslan</i>	
ISPARTA ARCHITECT SINAN MOSQUE'S ANALYSIS WITHIN THE CONSERVATION	2825
<i>H. Gokhan Kutlu, Ö. Coşkun Öner, Ö. Başagaç</i>	
REUSE AND RESTORATION OF A HOUSE IN BUCA KASAPLAR SQUARE, IZMIR, TURKEY	2835
<i>E. Omay Polat</i>	
RE-USING THE LAVUAR: ROUTE OF CULTURE	2844

NIKER AND PERPETUATE

*NEW INTEGRATED KNOWLEDGE BASED APPROACHES TO THE PROTECTION
OF CULTURAL HERITAGE FROM EARTHQUAKE-INDUCED RISK
and*

*PERFORMANCE-BASED APPROACH TO EARTHQUAKE PROTECTION
OF CULTURAL HERITAGE IN EUROPEAN AND MEDITERRANEAN COUNTRIES*

<i>C. Modena , S. Lagomarsino , F. da Porto , S. Cattari</i>	
EARTHQUAKE PROTECTION OF MASONRY HISTORICAL CONSTRUCTIONS: OVERVIEW OF RESULTS FROM NIKER AND PERPETUATE EUROPEAN PROJECTS	2851
<i>L. Cantini , F. da Porto , G. Giacometti , F. Lorenzoni , A. Saisi , M. R. Valluzzi</i>	
CREATION OF A STRUCTURED CATALOGUE	2861

<i>L. Miccoli, U. Müller, B. Silva, F. Da Porto, S. Hračov, S. Pospišil, C.-E. Adami, E. Vintzileou, G. Vasconcelos, E. Poletti</i>	
OVERVIEW OF DIFFERENT STRENGTHENING TECHNIQUES APPLIED ON WALLS USED IN HISTORICAL STRUCTURES.....	2870
<i>M.R. Valluzzi, P. Girardello, D. Francescato, S. Pospišil, R. Král, D. D'Ayala, S. Paganoni, L. Pelà, P. Roca, J. Branco, K. El Harrouni, B. Kucukdogan, M.A. Parisi</i>	
OPTIMIZATION OF DESIGN FOR FLOORS, ROOFS AND VAULTS	2879
<i>S. Paganoni, D. D'Ayala, L. Miccoli, S. Hračov, S. Urushadze, M. Wünsche, C.-E. Adami, E. Vintzileou, S. Moreira, D.V. Oliveira, P. James, V. Córias e Silva</i>	
CONNECTIONS AND DISSIPATIVE SYSTEMS WITH EARLY WARNING	2888
<i>E. Vintzileou, M.R. Valluzzi, N. Mazzon, S. Posipšil, L. Miccoli</i>	
SYSTEMIC IMPROVEMENT OF OVERALL SEISMIC RESPONSE	2897
<i>P. Roca</i>	
KNOWLEDGE-BASED SEISMIC ASSESSMENT OF ARCHITECTURAL HERITAGE.....	2906
<i>S. Cattari, S. Lagomarsino</i>	
PERFORMANCE-BASED APPROACH TO EARTHQUAKE PROTECTION OF MASONRY CULTURAL HERITAGE	2914
<i>C. Calderini, S. Abbati, S. Lagomarsino, R. Ginanni Corradini, V. Piovanello</i>	
INTERACTION BETWEEN STRUCTURAL CRACKS AND PLASTER DAMAGE: AN EXPERIMENTAL CAMPAIGN ON MASONRY PANELS”.....	2923
<i>G. De Canio, P. Clemente, M. Mongelli, I. Roselli, D. Rinaldis, F. Saitta, S. Lagomarsino, M. Rossi</i>	
PERFORMANCE BASED ASSESSMENT OF THE OBELISCO LATERANENSE IN ROME.....	2930
<i>V. I. Novelli, D. D'Ayala</i>	
SEISMIC VULNERABILITY ASSESSMENT OF THE CASBAH OF ALGIERS.....	2939
<i>S. Podestà, C. Romano</i>	
STRUCTURAL PRE-ANALYSIS FOR CULTURAL HERITAGE KNOWLEDGE PLANNING.....	2948
AUTHOR INDEX	XXXIII